i design	CLASSIFICATION ON THE TRANSPORT AND THE ROLL	US OFFICIALS ONLY	50X1-HUM
· · · · · · · · · · · · · · · · · · ·	Sanitized Copy Approved for Release 2011/05/17	1 : CIA-RDP82-00457R002800250006 AGENCY REPORT	5-2
May	INFORMATION RE	EPORT CD NO.	
COUNTRY	USSR (East Prussia)	DATE DISTR. ,2 J	une 49
SUBJECT	Schichau Werft, Kaliningrad	NO. OF PAGES 2	
PLACE		NO. OF ENCLS.	
ACQUIRED		(LISTED BELOW)	50X1-HUM
DATE OF INF			
This document co of the united sta U. S. C., DI and S2.	NTAINS INFORMATION AFFECTING THE NATIONAL DIFFERSE AT SO AS ALEMODE. NO TRANSMISSION OF THE REPUBLICANT OF THE STRUCTURE AT SO ALEMODE. NO TRANSMISSION OF THE REVELENTOR STRUCTURE AT SO ALEMODE.		
	AS INCRUMENT IS CANSHISSION OR THE REVELATION ANY HARMER TO AN URAUTHORIZED PERSON IS PRO-	IIS IS UNEVALUATED INFORMATION	
			50X1-HUM
	Installations Schichau Werft, Kal	iningrad	
1.	Shed No. 39, which contained the pipe f building which has been completely dost	itting shop, is the only	
2,		nd 15a (the come)	
3.	Two large sheds alongside the submarine were formerly used for storing su marine by the Sovieta. Lathes, joiner's benche machines were then installed. The sheds of the yard with barbod wire, German prisoners-of-war were employed the ship's pumps. A carpenter's shop was seffittings.	e spare parts, were cleared out es, milling machines, and drill: s were barricaded from the rest some 200	50X1-HUM
	Shed No. 97, an installation for the chais completely intact. It has 12 generat 600 amps. Although the installation is not used.	COMM. A man trickly a man and the comment	·
(The cable shop is intact; and the former station housed here is now used as a sch some 200 boys and 100 girls between the in radio operation.	OOL for admilland and	9 d
-	The yard power station, housed in the tucompletely intact. One turbine of 6,000 are two turbines of 1,200 KW each in she set in motion and run for helf a day. testing purposes only. All electrical is and the network of cables is undamaged.	KW is installed there. There d No. 48. Both are periodically This is reported by done for	
CTATE I.	CLASSIFICATION COSUCROM/POWEROL-U	S OFFICIALS ONLY	
ARMY >	MANY # NSRB DISTRIBUTION AIR FBI		
gove per range frame man un		Document No	······································
		NO CHANGE in Class. DECLASSIFIED	50X1-HUM
		Class. CHANCED TO: TS	s (T)
		DDA Meno, 4 Apr 77 Auth: DDA REG. 77/1764	<u>-</u>

Date: MAY 19 By: Sanitized Copy Approved for Release 2011/05/11 : CIA-RDP82-00457R002800250006-2 Sanitized Copy Approved for Release 2011/05/11 : CIA-RDP82-00457R002800250006-2 1-HUM

CONSEDENTACEMENT OF THE CONTROL OF T CENTRAL INTELLIGENCE AGENCY

	- 2 -				
7	. The testing shops for ship's diesels and machinery, housed in shed No. 5 are intact, but not in use.	7,			
8.	Seventy per cent of the mechanical workshops in shed No. 50; equipped with lathes, drills, and milling machines, are in action.				
9.	The electro-welding plant in shed No. 26 is in full service. Soviets, principally women, are being trained in electro-welding in this plant.				
10.	The sawmill in shed No. 11 is in service and has been extended by the installation of a second band saw (Gatter).				
11.	Sheds 40 and 41 (ship construction) are undamaged and partly in service.				
12.	Shed No. 42, the joiner's shop, is in service.				
13.	The shed in which acetylene is produced is undamaged and in full production.				
	Motor Torpedo Prefabrication Program 50X1-HUM				
14.	of a motor torpedo boat hull and two superstructure sections have been assembled alongside. but they have not been welded together.				
	Similarly, no work is being undertaken in the sheds which were formerly used for the assembly of sections and sub-sections. There are no indications that any work was undertaken on the motor torpedo boat programular that sufficient materials appear to be available and a number of completed sections are already lying in the sheds. The cause for this standstill is the complete incompetence of Soviet engineers and workmen.	[™] 50X1-HUM			
	Submarines				
15.	The tank installations for submarines were completely destroyed. no submarines came to the yard for repairs, and no submarine sections were assembled.	50X1-HUM 50X1-HUM			
16。	A completed submarine lies beached alongside the submarine harbor. The greater part of its equipment has been removed.				
17.	A number of submarine sections, delivered from yards at Gdansk or Gdynia, are lying about the yard. They have been completely cannibalized; everything of value has been stolen by the workers.				
	Miscellaneous				
18.	The only craft to undergo repairs at the Schichau Werft were a few motor torpedo b cats, smaller gunboats, and	50X1-HUM			
19.	The total number of Soviet workers at the Schichau Werft was about 800, excluding apprentices from the training work shop and the trainess from the radio school in the cable chop.	50X1-HUM			
20。	the yard presented a very derelict appearance The Russians had carried out a number of excavations throughout the yard, laying bare the electric cables	-HUM			
	the yard was fully maintained and had a good group of marking at though 50X1.	TIOIVI			

CONSTRUCTOR OFFICIALS ONLY



the yard was fully maintained and had a good stock of machinery, its capital 50X1-HUM